

Translations:Eolienne 200W/140/en

- Draw a circle of radius slightly greater than 40mm on the metallic disc to center the spindle's base on the cradle.

Fix the two part temporarily with a few soldering points. Make the 4 drills across the base of the spindle and the cradle.