For the assembly of the food storage furniture, an air gap of 3-4cm is to be integrated into back side in order for "exhaust" air and humidity to flow and not stagnate, risking quicker spoilage.