## Translations: L'éolienne/146/en

In general, the more steps the motor has, the less important the rotating speed at constant voltage. Here are the technical characteristics that are important in the choice of the motor: - The maximal or nominal output voltage (measured in volts): Vmax - The current per phase (measured in ampers / phase): A/ph - The number of steps or the step angle (measured in °)