

Translations:Bélier hydraulique/121/en

-Place male fittings on each side on the valve to avoid damaging it during the operation