Translations: Bélier hydraulique/25/en

Pierce the arc pieces and the base at the good spots in order to obtain a good clamping but not excessive (it would damage the pipes).