

Translations:Bio Charbon/25/en

The temperature will then rise to around 280°C. This phase is called endothermic reaction, where energy is needed to work. This energy is supplied by the complete combustion of a small part of the straws in the carbonisation machine. The dryer the straws, the less energy will be necessary.