

Translations:Eolienne 200W/222/en

Note: This step consists of gluing together strong magnets on the steel disk by **alternating the poles of the magnets**. If the alternation is not respected, the generator will not function and there is risk of damage.