

Translations:L'éolienne/130/en-gb

1 - Solder the negative pole of the capacitor with the common of the voltage regulator. Solder the plus of the capacitor to the input of the voltage regulator. (*image 10*)