

Translations:Meuble lavabo autonome/35/en

 ...The threaded stem of the tap was too tight against the thickness of the chosen wood board, so a slight widening was necessary.