

Translations:Récupération de batteries/102/en

3) Repeat the same action with the positive cables of the converter and the battery, then weld the whole to the positive pole of the charge regulator. (*image 8*)